

MTW Aerospace, Inc.

Turbine Aircraft Parts

7050 Hwy 80 West
 Montgomery, AL 36108
 Phone: 334-613-2025 Fax 334-777-0078
 Email: phil@mtwaerospace.com
 Website: www.mtwaerospace.com

ENGINE DISC RECORD SHEET

APU MODEL: GTCP36-150DD
 APU S/N: P-275
 BUILD SPEC: 3800498-1

TSN: 9960
 CSN: NA
 TSO: NA
 CSO: NA
 TSR: 2282
 TSHSI: 5362

Repaired Oct 2006 Honeywell Intl PHX, APU TSN 4598, Mod back to 3800498-1
Inspect & Test Dec 2006 Honeywell Intl PHX APU TSN 4728
Repaired Jan 2011 Piedmont Aviation APU TSN 7678
Removed from Service Nov 2013 for 10000 Hr Check APU TSN 9960

LIFE LIMITED COMPONENTS LISTING (LLC)

COMPONENT	P/N	SN	LIFE LIMIT	TSN	TR
TURBINE ROTOR	3615880-1	000134513445	10000	9960	40
COMPRESSOR ROTOR	3822101-1	021365105190	100000	9960	90040

ACCESSORIES

Part	Part No.	Serial	TS Install	Cond @ Instl
Surge Valve	109812-13	unk	UNK	
Fuel Control Unit	3882730-9	45679	UNK	
Pickup Transducer	3876104-1	292	UNK	
Fuel Flow Divider	3830166-1	NA	UNK	
Fuel Solenoid Valve	692545-17	4380	UNK	
Oil Temp Switch	3888030-1	000922705718	UNK	
Switch - Low Oil Press	3876001-8	unk	UNK	
Primary Fuel Nozzle #1	<i>Missing</i>	<i>Missing</i>	<i>Missing</i>	<i>Missing</i>
Primary Fuel Nozzle #2	<i>Missing</i>	<i>Missing</i>	<i>Missing</i>	<i>Missing</i>
Primary Fuel Nozzle #3	<i>Missing</i>	<i>Missing</i>	<i>Missing</i>	<i>Missing</i>
Secondary Fuel Nozzle #4	<i>Missing</i>	<i>Missing</i>	<i>Missing</i>	<i>Missing</i>
Secondary Fuel Nozzle #5	<i>Missing</i>	<i>Missing</i>	<i>Missing</i>	<i>Missing</i>
Secondary Fuel Nozzle #6	<i>Missing</i>	<i>Missing</i>	<i>Missing</i>	<i>Missing</i>
EGT Thermocouple	3876003-3	5-20219-980	UNK	
Ignition Lead	3888302-19	NA	UNK	
Ignition Box	3888000-2	010218025268	4489	O/H
Wiring Harness	3888385-1	NA	UNK	
APU Hour Meter	3888126-1	NA	UNK	